

Oil Field Environmental Incident Summary

Incident: 20140904183238 **Date/Time of Notice:** 09/04/2014 18:32

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: BRANDVIK 14-24H

Field Name: CORRAL CREEK

Well File #: 16460

Date Incident: 9/4/2014 **Time Incident:** 06:00

Facility ID Number:

County: DUNN

Twp: 147

Rng: 96

Sec: 24

Qtr:

Location Description:

Submitted By: Todd Senescall

Received By:

Contact Person: Todd Boepple
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Tank Overflow

Release Contained in Dike No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	7	Barrels	3	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

fire

Areal Extent:

Approximately 3/4 of acre of summer fallow and grass off of well location was lighting misted.

Potential Environmental Impacts:

vegetation and topsoil, location soil

Action Taken or Planned:

Notified area NDIC inspector via voicemail. Standing oil was sucked up. Smaller puddles were recovered with absorbent pads. Contaminated soil inside of secondary containment will be removed after the tanks are steamed. Misted vegetation will be mowed and bagged. White paper wipe sampling was done to determine the extent of the misting on vegetation. Soil sampling will be conducted to determine what other remediation may be warranted.

Wastes Disposal Location: Liquid - SWD
Soils - Chimney Butte

Agencies Involved:**Updates**

Date: 9/5/2014 **Status:** Reviewed; Followup Required **Author:** Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, got off location. Followup is necessary.

Date: 9/9/2014 **Status:** Inspected; More Followup Required **Author:** Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 43 °F, cloudy, with wind from the northeast at 10 mph. The spray occurred on the east side of pad. A small strip of vegetation is between the pad and field. This vegetation has been mowed and bagged. An area in the field has been flagged; nothing has been done in the field. The field was not seeded this year. More followup is needed to check on vegetation growth in the future.

Date: 10/30/2014 **Status:** Inspected; More Followup Required **Author:** Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 2:40 p.m. The weather was 36°F, overcast, with the wind 10 mph from the northwest. The grass bags have been hauled away. Area in field is still flagged off; nothing has been done. Further followup needed in the future.

Date: 11/19/2014 **Status:** Phone/Email Contact **Author:** Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Sample results of cleanup.

Date: 11/24/2014 **Status:** Phone/Email Contact **Author:** Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received sample results.